


ubuntu - Greške #13698

□ □

USR9602 USB Internet Mini Phone

27.03.2008 10:37 - Ernad Husremović

Status:	Zastarjelo	Početak:	27.03.2008
Prioritet:	Normalan	Završetak:	
Odgovorna osoba:	Ernad Husremović	% završeno:	0%
Kategorija:		Procjena vremena:	0.00 sat
Ciljna verzija:			
Opis			
			
http://www.usr.com/support/product-template.asp?prod=9602			
ne radi pod linux-om			
Povezani tiketi:			
korelira sa ubuntu - Podrška #13709: build linux-ubuntu-modules 2.6.24 hardy		Zastarjelo	27.03.2008

Historija

#1 - 27.03.2008 10:37 - Ernad Husremović

- Fajl 9602-setup-4.0.0.2.exe dodano

#2 - 27.03.2008 10:39 - Ernad Husremović

- Fajl 9602.jpg dodano

#3 - 27.03.2008 10:40 - Ernad Husremović

hernad@nmraka-1:~\$ lsusb
Bus 004 Device 003: ID 062a:9004 Creative Labs

#4 - 27.03.2008 10:59 - Ernad Husremović

<https://bugs.launchpad.net/ubuntu/+source/alsa-utils/+bug/116517>

#5 - 27.03.2008 17:49 - Ernad Husremović

```
static int init_usb_sample_rate(struct usb_device *dev, int iface,
                               struct usb_host_interface *alts,
                               struct audioformat *fmt, int rate)
{
    unsigned int ep;
    unsigned char data[3];
    int err;

    ep = get_endpoint(alts, 0)->bEndpointAddress;
    /* if endpoint has sampling rate control, set it */
    //hernad: comment: if (fmt->attributes & EP_CS_ATTR_SAMPLE_RATE) {
    if (0) {
        int crate;
        data[0] = rate;
        data[1] = rate >> 8;
        data[2] = rate >> 16;
        if ((err = snd_usb_ctl_msg(dev, usb_sndctrlpipe(dev, 0), SET_CUR,
                                  USB_TYPE_CLASS|USB_RECIP_ENDPOINT|USB_DIR_OUT,
```

```

        SAMPLING_FREQ_CONTROL << 8, ep, data, 3, 1000)) < 0) {
    snd_printk(KERN_ERR "%d:%d:%d: cannot set freq %d to ep 0x%x\n",
        dev->devnum, iface, fmt->altsetting, rate, ep);
    return err;
}
if ((err = snd_usb_ctl_msg(dev, usb_rcvctrlpipe(dev, 0), GET_CUR,
    USB_TYPE_CLASS|USB_RECIP_ENDPOINT|USB_DIR_IN,
    SAMPLING_FREQ_CONTROL << 8, ep, data, 3, 1000)) < 0) {
    snd_printk(KERN_WARNING "%d:%d:%d: cannot get freq at ep 0x%x\n",
        dev->devnum, iface, fmt->altsetting, ep);
    return 0; /* some devices don't support reading */
}
crate = data[0] | (data[1] << 8) | (data[2] << 16);
if (crate != rate) {
    snd_printd(KERN_WARNING "current rate %d is different from the runtime rate %d\n",
crate, rate);
        // runtime->rate = crate;
    }
}
return 0;
}

```

```

hernad@nmraka-1:/data/home/hernad/devel/ubuntu/hardy$ dpkg-buildpackage -nc
hernad@nmraka-1:/data/home/hernad/devel/ubuntu/hardy$ sudo dpkg -i linux-ubuntu-modules-2.6.24-12-generic_2.6.24-12.17_amd64.deb

```

```

hernad@nmraka-1:~$ cat /proc/asound/cards
0 [NVidia      ]: HDA-Intel - HDA NVidia
HDA NVidia at 0xf2680000 irq 21
1 [U0x62a0x9004 ]: USB-Audio - USB Device 0x62a:0x9004
USB Device 0x62a:0x9004 at usb-0000:00:04.0-2, full speed

```

#6 - 27.03.2008 17:58 - Ernad Husremović

<http://defectivecompass.wordpress.com/2007/12/16/pulseaudio-alsa-configuration/>

#7 - 27.03.2008 18:02 - Ernad Husremović

```

hernad@nmraka-1:~$ cat /proc/asound/cards

```

```

0 [NVidia      ]: HDA-Intel - HDA NVidia
HDA NVidia at 0xf2680000 irq 21
1 [U0x62a0x9004 ]: USB-Audio - USB Device 0x62a:0x9004
USB Device 0x62a:0x9004 at usb-0000:00:04.0-2, full speed

```

```

hernad@nmraka-1:~$ cat /proc/asound/devices

```

```

0: [ 0] : control
1:      : sequencer
4: [ 0- 0]: hardware dependent
5: [ 0- 1]: hardware dependent
16: [ 0- 0]: digital audio playback
24: [ 0- 0]: digital audio capture
32: [ 1] : control
33:      : timer
48: [ 1- 0]: digital audio playback
56: [ 1- 0]: digital audio capture

```

#8 - 06.04.2008 11:54 - Ernad Husremović

- Odogovorna osoba postavljeno na Ernad Husremović

međutim uređaj, iako je sada detektovan ne radi, ovaj paket mi je prvio probleme pa sam ga ubrzo uklonio i instalirao standardni paket iz repos-a

#9 - 10.11.2008 10:54 - Ernad Husremović

- Status promijenjeno iz Novo u Zastarjelo

Fajlovi

Ime fajla	Velčina	Datum	Autor
9602-setup-4.0.0.2.exe	1,06 MB	27.03.2008	Ernad Husremović
9602.jpg	5,94 KB	27.03.2008	Ernad Husremović